

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:01/30/2025 16:21:46

Technician Name:Hennie

## Vehicle Information

Make:BENZ

Model:205.014 - C 220 d Sedan

VIN:WDD2050142R465430

Displacement:G 1.2 MPI KAPPA

Odometer:111998 miles

Vehicle Software Version:V10.98

## Inspection Result

The following systems are OK:

- 1.PTCU - Drivetrain
- 2.FSCU - Fuel Pump
- 3.CDI - Engine Control Module(ECM)
- 4.SCR - Selective Catalytic Reduction
- 5.VGS/DKG/DCT - Transmission Control Unit (TCM)
- 6.AML - Ambiance Light
- 7.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 8.LIN bus: AISP - Dimming Inside Rearview Mirror
- 9.B95 (Battery sensor)
- 10.B38/2 (Rain/light sensor with additional functions)
- 11.Windshield wiper
- 12.REAR SAM - Rear Signal Acquisition And Actuation Module
- 13.N25/17 (Front seat heater/seat ventilation control unit)
- 14.EIS/EZS - Electronic Ignition Lock
- 15.SG-SW\_L - Left Headlamp
- 16.SG-SW\_R - Right Headlamp
- 17.KG - KEYLESS GO
- 18.OCP - Overhead Control Panel
- 19.LIN bus: AS - Alarm Siren
- 20.AB - Supplemental Restraint System
- 21.SCM - Steering Column Module
- 22.LRE - Steering Wheel Electronics
- 23.SD - Control Module Sliding Roof
- 24.Active Brake Assist
- 25.MFK - Multifunction Camera
- 26.PTS - PARKTRONIC