

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 17729

Make	MAZDA		
Model	MAZDA2 1.5 INDIVIDUAL PLUS / HAZUMI A/T		
Vin	MM6DJ2HAAJW3675	541	
Engine Specifications	1.5	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2018
Km	95817
Transmission	Automatic
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	•
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	•
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Renewed	•

BOSCH VEHICLE INSPECTION

Oil Service		95817 Km	Dip Stick	Within Specification	•
Oil Filter	Renewed	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	No Cracks	•
Air Filter	Within Specification	-	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	-	Alternator Belt	Renewed	•
Spark Plugs	Within Specification	-	Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification	-	Aircon Belt	Within Specification	•
Antifreeze	Within Specification	~	Multi V belt	Not Applicable	•
Rear Main Seal	No Visible Leaks	-	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	-	PCV Valve	Within Specification	•

BOSCH INSPECTION REPORT

•

•

•

•

•

•

◄

•

•

•

•

•

Braking System	
Front Brake Pads	60%
Front Brake Discs	Within Specification
Front Brake Sensor	Not Applicable
Rear Brake Pads	-Select-
Rear Brake Discs	Not Applicable
Rear Brake Sensor	Not Applicable
Rear Drums	Within Specification
Rear Linings	80%
Brake Master	Within Specification
Hand Brake	Within Specification

BOSCH Service

Brake Calipers

Brake Hose

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	-
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Within Specification

Within Specification

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Not Applicable	•

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	Not Applicable	-
Road Test	Within Specification	•
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

NEW Technician

-Select-

HENNIE

General Comments

Date of Inspection

13-Dec-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

