

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:11/07/2024 13:51:00

Technician Name:Ricardo

Vehicle Information

Year:2017

Make:USAFORD

Model:Everest

VIN:AFAJXXMJWJHB68244

Displacement:D 2.5 TCI-A2

Odometer:132665 km

Vehicle Software Version:V10.86

Inspection Result

The following systems are OK:

- 1.ABS (Anti-Lock Braking System)
- 2.ACM (Audio Control Module)
- 3.APIM (Accessory Protocol Interface Module)
- 4.BCMII (Body Control Module)
- 5.DACM-C (Digital Audio Control Module C)
- 6.FCIM (Front Controls Interface Module)
- 7.GWM (Gateway Module A)
- 8.IPC (Instrument Panel Control Module)
- 9.PAM (Parking Aid Module)
- 10.PCM (Powertrain Control Module)
- 11.PSCM (Power Steering Control Module)
- 12.RCM (Restraint Control Module)
- 13.RHVAC (Rear Heating Ventilation Air Conditioning)
- 14.RTM (Radio Transceiver Module)
- 15.SCCM (Steering Column Control Module)
- 16.TCCM (Transfer Case Control Module)
- 17.TCM (Transmission Control Module)
- 18.TRM (Trailer Module)