

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:juan-dre@boschgezina.co

Sn:988579800333

Time:2024-07-12 09:09:02

Technician Name:Raymond

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2014

Make:JEEP

Model:Grand Cherokee

VIN:1C4RJFHJ5EC369401

Displacement:G 1.6 MPI

Odometer:105750 km

Vehicle Software Version:V10.50

## Inspection Result

BCM (Body Control Module - TIPMCGW/FCMCGW) 1 problems exist

**1.U0167-00 Lost Communication With Intrusion Transceiver Control Module** **Active**

The following systems are OK:

- 1.PCM (Powertrain Control Module)
- 2.TCM (Transmission Control Module)
- 3.IPC (Instrument Panel Cluster)
- 4.RFH/TPMS (Radio Frequency Hub - Tire)
- 5.ABS (Anti-lock Braking System)
- 6.SRS (Supplemental Inflatable Restraint System - ORC (Occupant Restraint Controller))
- 7.TPMS (Tire Pressure Monitoring System)
- 8.ACC (Adaptive Cruise Control)
- 9.PTS (Park Tronics)
- 10.AFLS (Adaptive Front Lighting System)
- 11.SCCM (Steering Column Control Module)
- 12.ESM (Electronic Shifter Module)
- 13.FFCM (Forward Facing Camera Module)
- 14.DTCM (Drive Train Control Module)
- 15.ELSD (Electronic Limited Slip Differential)
- 16.ADCM (Active Damping Control Module)
- 17.HVAC (Heating Ventilation Air-conditioning And Cooling)/AC (Air Conditioner)
- 18.Radio

- 19.AMP (Amplifier)
- 20.DDM (Drivers Door Module)
- 21.PDM (Passengers Door Module)
- 22.MSMD (Memory Seat Module)
- 23.HSM (Heated Seat Module)
- 24.LBSS (Left Blind Spot Sensor)
- 25.ICS (Integrated Center Stack)
- 26.EDM (External Disc Module)
- 27.PLGM (Power Lift Gate Module)