

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: jaco@boschgezina.co.za

Sn: 988579800333

Time: 2024-07-25 09:15:29

Technician Name: Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Make: BENZ

VIN: WDD1760082J715130

Displacement: G 1.0 MPI KAPPA

Odometer: 114840 km

Vehicle Software Version: V10.76

Inspection Result

IC - Instrument cluster(A1) 1 problems exist

1.U11A687 Communication with control unit "Radar sensorics" has a malfunction. The message is missing. N/A

The following systems are OK:

1. CDI - Commonrail Diesel Injection system(ECM)

2. FSCU_EC - Control Unit 'Fuel pump'(N118)

3. Y3/8 - Transmission control for 9-speed transmission(VGS)

4. PTCU - Drivetrain

5. EPB - Electrical Parking Brake(EPB)

6. ESP - Electronic Stability program(N30/4)

7. ES - Electrical Power Steering(N68)

8. TPC - Tire Pressure Monitoring System(TPMS)(N88)

9. EIS/EZS - Electronic Ignition lock(N73)

10. SG_AWF - Control Unit 'COLLISION PREVENTION ASSIST'(A90)

11. SAM - Signal Acquisition And Actuation module(N10)

12. AB - Supplemental Restraint system(N2/10)

13. ATA - ATA[EDW]/tow-away Protection/Interior protection(N26/6)

14. SG-SW_L - Left Headlamp

15. SG-SW_R - Right Headlamp

16. KG - KEYLESS GO(N69/5)

17. SD - Sliding Roof/Panoramic Sliding Sunroof

18. Control Unit For Telematics Services

19. MFK - Multifunction camera(A40/11)

20. SCM - Steering Column module(N80)

- 21.PTS - PARKTRONIC(N62)
- 22.ZBE - Operating Unit Of Control Unit'Audio Or COMAND'(A40/9)
- 23.ZAN - Audio/COMAND display(A40/8)
- 24.Audio 20/COMAND-Audio Or COMAND(A2-A40/3)
- 25.DCU_LF - Left Front door(N69/1)
- 26.DCU_RF - Right Front door(N69/2)
- 27.AC - Air Conditioning(N22/7)
- 28.LIN: N70 - Overhead control panel(OCP)
- 29.LIN: B95 - Battery sensor(BSN)
- 30.LIN: B38/2 - Rain/light sensor(RGLS)
- 31.LIN: N72/1 - Upper control panel(UCP)
- 32.LIN: H3/1 - Alarm siren (AS)