

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

shop Name:  
Address:  
Telephone:N/A  
Sn:988579800333  
Time:11/26/2024 12:10:33  
Technician Name:John

## Vehicle Information

Make:BENZ  
Model:253.905 - GLC 220 d 4MATIC Off-Roader  
VIN:WDC2539052F572852  
Odometer:56127 km  
Vehicle Software Version:V10.98

## Inspection Result

The following systems are OK:

- 1.PTCU - Common Powetrain Controller
- 2.CDI - Engine Control Module(ECM)
- 3.FSCU - Fuel Pump
- 4.VGS/DKG/DCT - Transmission Control Unit (TCM)
- 5.Driver-side SAM - Front Signal Acquisition And Actuation Module
- 6.B95 (Battery sensor)
- 7.B38/2 (Rain/light sensor with additional functions)
- 8.N70 (Overhead control panel control unit)
- 9.Windshield wiper
- 10.REAR SAM - Rear Signal Acquisition And Actuation Module
- 11.EIS/EZS - Electronic Ignition Lock
- 12.SG-SW\_L - Left Headlamp
- 13.SG-SW\_R - Right Headlamp
- 14.AB - Supplemental Restraint System
- 15.SCM - Steering Column Module
- 16.AHE - Trailer Recognition Module
- 17.ATA - Interior Motion Sensor
- 18.LIN bus: AS - Alarm Siren
- 19.PTS - PARKTRONIC
- 20.RFK - Backup Camera
- 21.TPC - Tire Pressure Monitoring System(TPMS)
- 22.N68 - Electrical Power Steering (ES)
- 23.ESP - Electronic Stability Program
- 24.KAB - Camera Cover
- 25.COU[ZBE] - Audio/COMAND Operating Unit
- 26.N72/1 (Upper control panel control unit)
- 27.N72/5 (Right lower control panel)