

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:citton cars
Address:564 Steve Biko Road
Telephone:0123355737
Email:karika@boschgezina.co.za
Sn:988579800333
Time:2024-05-17 09:55:15
Technician Name:shaun
Order no:
Service fee:
Notes:

Vehicle Information

Make:INDIANMAHINDRA
VIN:MA1YV2HKUL6077711
Displacement:G 1.4 MPI
Odometer:68227 km
Vehicle Software Version:V10.34

Inspection Result

MBFM(BODY FUNCTION MODULE) 1 problems exist

1.U1108 IS Node Absent

CURRENT

ABS(ANTI-LOCK BRAKING SYSTEM) 1 problems exist

1.U300616 Under Voltage Error

OTHERS

The following systems are OK:

- 1.EMS(ENGINE MANAGEMENT SYSTEM)
- 2.IC(INSTRUMENT CLUSTER)
- 3.SRS(SUPPLEMENTARY RESTRAINT SYSTEM)
- 4.IMMOBILISER