

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre  
Address: 564 Steve Biko Road  
Telephone: 0123355737  
Email: juan-dre@boschgezina.co.za  
Sn: 988579800333  
Time: 2024-10-03 14:53:29  
Technician Name: Riaan  
Customer Name: citton cars  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Make: VW  
VIN: WVGZZZ5NZKM178911  
Displacement: G 1.4 MPI KAPPA  
Odometer: 52660 km  
Vehicle Software Version: V10.23

## Inspection Result

15 Airbag 1 problems exist

**1.B10071B Front Passenger Side Seat Belt Tension Igniter - Resistance Too High** **Active/Static**

The following systems are OK:

1.01 Engine Electronics  
2.02 Transmission Electronics  
3.03 Brake Electronics  
4.08 Climate Control Module  
5.09 Electronic Central Electric  
6.17 Instrument Cluster  
7.19 Data Bus OBD Interface  
8.20 High Beam Assistant  
9.42 Driver's Door Electronics  
10.44 Power Steering  
11.52 Passenger's Door Electronics  
12.5F Information Electronics 1  
13.65 Tire Pressure Monitoring System (TPMS)