

Diagnostic Report

THINKCAR

Time: 11/11/2024 09:39:12

Customer Name: N/A

Technician Name: mike

Shop Name: Bosch Gezina	Telephone: N/A
Email: karika@bosch	Country: South Africa
State: Gauteng	City: Pretoria
Address1: N/A	Address2: N/A

Make: SMART	Model: Gasoline engine
Year: N/A	Displacement: G 1.2 MPI KAPPA PE
VIN: WME4530422Y085534	Odometer: 46669 km
License #: N/A	Vehicle Software Version: V10.14

Pre-Scan

11/11/2024 09:39:12

System(10)	Status(3)
ME - Motor electronics(ME17_453)	Fault 3
ES - Electrical Power Steering (N68)	No Fault
ESP - Electronic Stability Program	No Fault
Driver-side SAM - Signal Acquisition And Actuation Module (N10/11)	No Fault
SAM-M - Signal Acquisition And Actuation Module (N10/10)	No Fault
SRS - Supplemental Restraint System (N2/10)	No Fault
AGW - Audio Gateway	No Fault
Audio - Audio Or COMAND (A2)	No Fault
IC - Instrument Cluster (A1)	No Fault
AAC - Air Conditioning	No Fault

DTC

System	Code	Description	Status
ME - Motor electronics(ME17_453)	P1525F3	Component "CRUISE CONTROL" reports a fault.	STORED
ME - Motor electronics(ME17_453)	P060AF1	The monitoring function in the control unit has a malfunction.There is an internal component fault.	STORED
ME - Motor electronics(ME17_453)	P155596	There is currently no further information available on this fault code.	STORED