

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:2024-08-13 07:55:58

Technician Name:Dries

Order no:

Service fee:

Notes:

Vehicle Information

Year:2015

Make:JEEP

Model:Grand Cherokee

VIN:1C4RJFGG4FC868522

Displacement:G 2.0 NU MPI

Odometer:103807 km

Vehicle Software Version:V10.50

Inspection Result

The following systems are OK:

- 1.PCM (Powertrain Control Module)
- 2.TCM (Transmission Control Module)
- 3.BCM (Body Control Module - TIPMCGW/FCMCGW)
- 4.IPC (Instrument Panel Cluster)
- 5.RFH/TPMS (Radio Frequency Hub - Tire)
- 6.ABS (Anti-lock Braking System)
- 7.SRS (Supplemental Inflatable Restraint System - ORC (Occupant Restraint Controller))
- 8.TPMS (Tire Pressure Monitoring System)
- 9.ACC (Adaptive Cruise Control)
- 10.PTS (Park Tronics)
- 11.DTCM (Drive Train Control Module)
- 12.ESM (Electronic Shifter Module)
- 13.SCCM (Steering Column Control Module)
- 14.EPS (Electronic Power Steering)
- 15.AFLS (Adaptive Front Lighting System)
- 16.ASCM (Air Suspension Control Module)
- 17.FFCM (Forward Facing Camera Module)
- 18.HVAC (Heating Ventilation Air-conditioning And Cooling)/AC (Air Conditioner)
- 19.Radio
- 20.AMP (Amplifier)
- 21.DDM (Drivers Door Module)

- 22.PDM (Passengers Door Module)
- 23.MSMD (Memory Seat Module)
- 24.ITM (Intrusion Transceiver Module)
- 25.LBSS (Left Blind Spot Sensor)
- 26.PLGM (Power Lift Gate Module)
- 27.RBSS (Right Blind Spot Sensor)
- 28.ICS (Integrated Center Stack)
- 29.HSM (Heated Seat Module)
- 30.EDM (External Disc Module)