

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: johan@boschgezina.co.za

Sn: 988579800333

Time: 2024-09-30 09:08:45

Technician Name: Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Year: 2022.03

Make: BMW

Model: M135i xDrive

VIN: WBA7L120707K88516

Displacement: G 1.0 T-GDI KAPPA

Odometer: 29669 km

Vehicle Software Version: V10.46

Inspection Result

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.TRVC (All Round View Camera)
- 3.HC/SWW (Lane Change Warning)/SRR_HR (Rear Radar Sensor Near Range Right)
- 4.HKFM/HKL (Automatic Luggage Compartment Lid Actuation)
- 5.ZGM (Central Gateway Module)
- 6.ECM (Engine Control Module - DME/DDE)
- 7.TCM (Transmission Control Module - EGS)
- 8.LMV/VTG (Transfer Case)
- 9.ABS (Anti-Lock Braking System - DSC)
- 10.EPB (Electrical Parking Brake - EMF)/SRR_HL (Rear Radar Sensor Near Range Left)
- 11.PMA (Parking Assistant)
- 12.EPS (Electronic Power Steering)
- 13.AMP (Amplifier)
- 14.ICMV (Vertical Dynamics Management)/VIP (Virtual Integration System)
- 15.CAS (Car Access System - CAS/FEM/BDC)
- 16.LHML (LED Main Light Module, Left)
- 17.LHMR (LED Main Light Module, Right)
- 18.FZD (Function Center, Roof)
- 19.KAFAS (Camera Based Driver Assist Systems)
- 20.GWS (Gear Selector Switch)
- 21.IC (Instrument Cluster - INSTR)

- 22.ECALL (Emergency Call)
- 23.CIC (Car Information Computer)
- 24.ZBE/CON (Controller)
- 25.FAS (Seat Module, Driver)
- 26.AC (Air Conditioning - IHKA)