

# Diagnostic Report

THINKCAR

Time: 01/08/2025 12:55:35

Customer Name: N/A

Technician Name: mike

Shop Name: Bosch Menlyn	Telephone: N/A
Email: Mike	Country: South Africa
State: Gauteng	City: Pretoria
Address1: 109 Atterbury ave	Address2: N/A

Make: MAZDA	Model: CX-5
Year: 2021	Displacement: N/A
VIN: JM6KF2W7AM0689236	Odometer: 48923 km
License #: N/A	Vehicle Software Version: V10.38

## Pre-Scan

01/08/2025 12:55:35

System(11)	Status
F_BCM (Front Body Control Module)	No Fault
IC (Instrument Cluster)	No Fault
PCM (Powertrain Control Module)	No Fault
RCM (Restraint Control Module)	No Fault
TCM (Transmission Control Module)	No Fault
ABS (Anti-Lock Brake System)	No Fault
AFS/ALM (Adaptive Front Lighting System/Auto Leveling Module)	No Fault
CMU (Connectivity Master Unit)	No Fault
EPB (Electrical Parking Brake)	No Fault
EPS (Electronic Power Steering)	No Fault

SSU#1 (Start Stop Unit)

No Fault