

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre
Address:564 Steve Biko Road
Telephone:0123355737
Email:mariska@boschgezina.co.za
Sn:988579800333
Time:2024-10-02 11:42:35
Technician Name:Raymond
Order no:
Service fee:
Notes:

Vehicle Information

Make:CHANGCHENG
Model:HAVAL H2 2012-2019(B
VIN:LGWEE4A45KH904079
Displacement:G 1.1 MPI
Odometer:059481 km
Vehicle Software Version:V10.38

Inspection Result

BCM 8 problems exist

- 1.B14DA96 FL Tire Sensor Missing
- 2.B14DB96 FR Tire Sensor Missing
- 3.B14DC96 RL Tire Sensor Missing
- 4.B14DD96 RR Tire Sensor Missing
- 5.B14DA96 FL Tire Sensor Missing
- 6.B14DB96 FR Tire Sensor Missing
- 7.B14DC96 RL Tire Sensor Missing
- 8.B14DD96 RR Tire Sensor Missing

- Current Fault Code
- Current Fault Code
- Current Fault Code
- Current Fault Code
- History Fault Code
- History Fault Code
- History Fault Code
- History Fault Code

The following systems are OK:

- 1.ECM
- 2.TCU (Transmission Control Unit)
- 3.ABS/ESP
- 4.SRS
- 5.EPS
- 6.ESCL
- 7.GW (Independent Gateway)
- 8.PEPS
- 9.RVC
- 10.IP
- 11.AC (Air Conditioning)
- 12.SAS

