

# Diagnostic Report

THINKCAR

Time: 10/22/2024 14:32:56

Customer Name: N/A

Technician Name: mike

Shop Name: Bosch Menlyn	Telephone: 0723428163
Email: jonesservicessa@gmail	Country: South Africa
State: Gauteng	City: Pretoria
Address1: N/A	Address2: N/A

Make: RENAULT	Model: TRIBER
Year: N/A	Displacement: D 2.5 TCI-A2(Euro-5)
VIN: MEERBC00X00165282	Odometer: 81199 km
License #: N/A	Vehicle Software Version: V10.40

## Pre-Scan

10/22/2024 14:32:56

System(7)	Status
ECM (Engine Control Module)	No Fault
ABS (Anti-lock Braking System)	No Fault
IC (Instrument Cluster)	No Fault
UCH	No Fault
SRS (Supplemental Inflatable Restraint System)	No Fault
Variable P.A.S	No Fault
Hands-Free Module	No Fault