

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:2024-08-27 15:23:09

Technician Name:Ricardo

Order no:

Service fee:

Notes:

Vehicle Information

Year:2015

Make:HYUNDAI

Model:Tucson/ix35(LM)

VIN:KMHJT81ELFU000147

Displacement:G 2.0 MPI

Odometer:124343 km

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-lock Braking System)
- 3.Airbag(Event #1)
- 4.Airbag(Event #2)
- 5.BCM (Body Control Module)
- 6.Smart Junction Block
- 7.EPS (Electronic Power Steering)
- 8.IMM (Immobilizer)
- 9.Transmitter Code Saving