

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Sn:988579800333
Time:02/05/2025 10:58:37
Technician Name:dries

Vehicle Information

Make:NISSAN
Displacement:G 1.2 MPI KAPPA
Odometer:136789 km
Vehicle Software Version:V10.48

Inspection Result

Engine Control Module(ECM) 3 problems exist	
1.P0380 Preheating unit DIAG CONN	PRESENT
2.P3264 Water in diesel w/l circ	PAST
3.P0170 Inj prog cycle not performed	PAST
Anti-lock Brake System(ABS) 1 problems exist	
1.C10CC COMPUTER SUPPLY VOLTAGE	N/A

The following systems are OK:

- 1.Body Control System(BCM)
- 2.Supplemental Restraint System(SRS)
- 3.Electric Power Steering(EPS)