

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: pieter@boschgezina.co.za

Sn: 988579800333

Time: 2024-10-03 12:36:40

Technician Name: Wimpie F

Order no:

Service fee:

Notes:

## Vehicle Information

Make: VW

VIN: WVGZZZC1ZLY023875

Displacement: G 1.2 DOHC

Odometer: 95016 km

Vehicle Software Version: V10.24

## Inspection Result

01 Engine Electronics 11 problems exist

1.P008700 Fuel Rail/System Pressure - Too Low	Passive/Sporadic
2.P014800 Fuel Delivery Error	Passive/Sporadic
3.P051200 Starter Request Circuit	Passive/Sporadic
4.P06E900 Engine Starter Performance	Passive/Sporadic
5.P030000 Random/Multiple Cylinder - Misfire Detected	Passive/Sporadic
6.P030100 Cyl.1 - Misfire Detected	Passive/Sporadic
7.P030200 Cyl.2 - Misfire Detected	Passive/Sporadic
8.U041600 ESP - Implausible Signal	Passive/Sporadic
9.U140A00 Terminal 30 - Open Circuit	Passive/Sporadic
10.P168000 Reset-Resistant Limp-Home	Passive/Sporadic
11.U350100 Control Module Input Power "A" Circuit Low	Passive/Sporadic

02 Transmission Electronics 1 problems exist

1.U140000 Function Restriction - Function Restriction Due To Low Voltage	Passive/Sporadic
--	------------------

08 Climate Control Module 2 problems exist

1.U140000 Function Restriction - Function Restriction Due To Low Voltage	Passive/Sporadic
2.B109211 Recirculation Flap Motor - Short Circuit To Ground (GND)	Passive/Sporadic

09 Electronic Central Electric 5 problems exist

1.B195329 Driver Side Rear Central Locking Lock Unit - Range/Performance	Passive/Sporadic
2.U10F400 Anti-Theft Alarm System Sensor - No Communication	Active/Static

3.B14D154 Front Drivers Side Window Regulator - No Basic Setting	Passive/Sporadic
4.B14D254 Front Passenger Side Window Regulator - No Basic Setting	Passive/Sporadic
5.B11F129 Window Regulator Button, Passenger Side - Range/Performance	Active/Static
15 Airbag 1 problems exist	
1.B13BCF2 Multiple Collision Brake - No Function	Passive/Sporadic
17 Instrument Cluster 2 problems exist	
1.B104C29 Key - Range/Performance	Passive/Sporadic
2.U101100 Supply Voltage - Voltage Too Low	Passive/Sporadic
19 Data Bus OBD Interface 4 problems exist	
1.U101100 Supply Voltage - Voltage Too Low	Passive/Sporadic
2.U141100 Battery Terminal Recognition - Open Circuit	Passive/Sporadic
3.B1802F1 NV-Energy Management - Alarm Triggered	Passive/Sporadic
4.U140600 Static Current - Too Large	Passive/Sporadic
55 Headlamp Range Control 2 problems exist	
1.U101100 Supply Voltage - Voltage Too Low	Passive/Sporadic
2.U140000 Function Restriction - Function Restriction Due To Low Voltage	Passive/Sporadic
5F Information Electronics 1 8 problems exist	
1.B126E13 Connection Between Radio And Antenna Amplifier 2 - Open Circuit	Active/Static
2.B110B12 Connections To Right Rear Speakers - Short Circuit To B+	Passive/Sporadic
3.B106413 Right Front Treble Speaker - Open Circuit	Active/Static
4.B110A12 Connections To Right Front Speakers - Short Circuit To B+	Passive/Sporadic
5.B106113 Left Front Treble Speaker - Open Circuit	Active/Static
6.B110912 Connections To Left Front Speakers - Short Circuit To B+	Passive/Sporadic
7.U140000 Function Restriction - Function Restriction Due To Low Voltage	Passive/Sporadic
8.B129B13 Microphone 1 - Open Circuit	Passive/Sporadic
76 Parking Aid 2 problems exist	
1.U101100 Supply Voltage - Voltage Too Low	Passive/Sporadic
2.U140000 Function Restriction - Function Restriction Due To Low Voltage	Passive/Sporadic
D6 Light Control Left 2 2 problems exist	
1.U101100 Supply Voltage - Voltage Too Low	Passive/Sporadic
2.U140000 Function Restriction - Function Restriction Due To Low Voltage	Passive/Sporadic
D7 Light Control Right 2 2 problems exist	
1.U101100 Supply Voltage - Voltage Too Low	Passive/Sporadic
2.U140000 Function Restriction - Function Restriction Due To Low Voltage	Passive/Sporadic

The following systems are OK:

1.03 Brake Electronics

2.44 Power Steering