

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:2024-09-03 07:53:48

Technician Name:Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Year:2013

Make:HYUNDAI

Model:ix35(EL)

VIN:TMAJU81VLDJ422878

Displacement:D 2.0 TCI-R

Odometer:66047 km

Vehicle Software Version:V10.30

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)(CPF-)
- 2.ECM (Engine Control Module)(CPF+)
- 3.ESP (Electronic Stability Program)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.Air Conditioner(EURO)
- 7.Air Conditioner(GEN)
- 8.BCM (Body Control Module)
- 9.Smart Junction Block
- 10.EPS (Electronic Power Steering)
- 11.IMM (Immobilizer)
- 12.Transmitter Code Saving