

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:citton cars  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:lukas@boschgezina.co.za  
Sn:988579800333  
Time:2024-04-06 12:10:58  
Technician Name:shaun  
Customer Name:cittoncars  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Make:TJTOYOTA  
Model:Avanza  
VIN:MHKM5EA2N0K004229  
Displacement:G 2.4 MPI  
Odometer:54975 km  
Vehicle Software Version:V10.44

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.EFI (Electronic Fuel Injection)
- 3.ABS (Anti-lock Braking System)/VSC (Vehicle Stability Control)
- 4.EPS (Electric Power Steering)
- 5.SS (Steering Sensor)
- 6.SRS (Supplemental Inflatable Restraint System)
- 7.IC (Instrument cluster)
- 8.BCM (Body Control Module)
- 9.CSW (Combination Switch)