

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:2024-09-05 14:28:54

Technician Name:shaun

Order no:

Service fee:

Notes:

Vehicle Information

Year:2018

Make:USAFORD

Model:Ranger / Mazda B-Ser

VIN:AFANXXMJ2NJT68911

Odometer:142420 km

Vehicle Software Version:V10.76

Inspection Result

IPC (Instrument Panel Control Module) 1 problems exist

1.U3003:16-08 Battery Voltage

Continuous Memory DTCs

PSCM (Power Steering Control Module) 1 problems exist

1.U3003:16-48 Battery Voltage

Continuous Memory DTCs

RCM (Restraint Control Module) 1 problems exist

1.U3003:16-08 Battery Voltage

Continuous Memory DTCs

The following systems are OK:

1.ABS (Anti-Lock Braking System)

2.ACM (Audio Control Module)

3.BCMII (Body Control Module)

4.FCIM (Front Controls Interface Module)

5.GWM (Gateway Module A)

6.PCM (Powertrain Control Module)

7.RTM (Radio Transceiver Module)

8.SCCM (Steering Column Control Module)

9.TRM (Trailer Module)