

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre  
Address:564 Steve Biko Road  
Telephone:0123355737  
Email:mariska@boschgezina.co.za  
Sn:988579800333  
Time:2024-10-15 13:48:49  
Technician Name:Raymond  
Order no:  
Service fee:  
Notes:

## Vehicle Information

Year:2019  
Make:VOLVO  
Model:V40 2013-  
VIN:YV1MV74H0K2571859  
Displacement:G 1.1 SOHC  
Odometer:76957 km  
Vehicle Software Version:V10.28

## Inspection Result

CEM (Central Electrical Module) 1 problems exist

**1.U030141 Software Incompatibility With ECM/PCM. System Internal Failures. General Checksum Failure**

The following systems are OK:

- 1.AUD (Audio Module)
- 2.CCM (Climate Control Module)
- 3.DDM (Driver Door Module)
- 4.ICM (Infotainment Control Module)
- 5.PDM (Passenger Door Module)
- 6.ABS (Anti-Lock Braking System)
- 7.CVM (Closing Velocity Module)
- 8.DIM (Driver Information Module)
- 9.PAM (Park Assist Module)
- 10.SAS (Steering Wheel Angle Sensor Module)
- 11.SRS (Supplemental Inflatable Restraint System)
- 12.TCM (Transmission Control Module)
- 13.DIESEL ENG (Fuel System/Combined System)
- 14.PSCM (Power Steering Control Module)