

All System Diagnostic Report

Pre-Scan

The Report is created by **THINKCAR**

Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:02/04/2025 11:39:24

Technician Name:dries

Vehicle Information

Year:2021

Make:TOYOTA

Model:Starlet

VIN:JTDGWC52S00718631

Displacement:G 1.2 MPI KAPPA

Odometer:63582 km

Vehicle Software Version:V10.36

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.ABS (Anti-Lock Braking System)
- 3.EPS (Electronic Power Steering)
- 4.SRS (Supplemental Inflatable Restraint System/Airbag)
- 5.BCM (Body Control Module)
- 6.IPC (Combination Meter / Meter/ M&A)
- 7.CGW (Central Gateway Control Module)