

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name: bosch service centre
Address: 564 Steve Biko Road
Telephone: 0123355737
Email: juan-dre@boschgezina.co.za
Sn: 988579800333
Time: 2024-09-16 16:16:56
Technician Name: Riaan
Customer Name: citton cars
Order no:
Service fee:
Notes:

Vehicle Information

Year: 2021
Make: EUROFORD
Model: EcoSport
VIN: WF01XXERK1MC79859
Displacement: G 1.4 DOHC
Odometer: 54799 km
Vehicle Software Version: V10.76

Inspection Result

The following systems are OK:

1. ABS (Anti-Lock Braking System)
2. ACM (Audio Control Module)
3. BCMII (Body Control Module)
4. GWM (Gateway Module A)
5. HVAC (Heating Ventilation Air Conditioning)
6. IPC (Instrument Panel Control Module)
7. PAM (Parking Aid Module)
8. PCM (Powertrain Control Module)
9. PSCM (Power Steering Control Module)
10. RCM (Restraint Control Module)
11. SCCM (Steering Column Control Module)
12. TCU1 (Telematic Control Unit Module)