

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:10/30/2024 10:54:02

Technician Name:Eugene

Vehicle Information

Year:2020.02

Make:BMW

Model:118i

VIN:WBA7K320407F88922

Odometer:63259 km

Vehicle Software Version:V10.30

Inspection Result

CAS (Car Access System - CAS/FEM/BDC) 1 problems exist

1.804415 Radio Remote Control: Battery Undervoltage

Permanent

The following systems are OK:

- 1.SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)
- 2.TRVC (All Round View Camera)
- 3.HKFM/HKL (Automatic Luggage Compartment Lid Actuation)
- 4.ZGM (Central Gateway Module)
- 5.ECM (Engine Control Module - DME/DDE)
- 6.TCM (Transmission Control Module - EGS)
- 7.ABS (Anti-Lock Braking System - DSC)
- 8.PMA (Parking Assistant)
- 9.EPS (Electronic Power Steering)
- 10.ICMV (Vertical Dynamics Management)/VIP (Virtual Integration System)
- 11.LHML (LED Main Light Module, Left)
- 12.LHMR (LED Main Light Module, Right)
- 13.FZD (Function Center, Roof)
- 14.GWS (Gear Selector Switch)
- 15.IC (Instrument Cluster - INSTR)
- 16.ECALL (Emergency Call)
- 17.CIC (Car Information Computer)
- 18.ZBE/CON (Controller)
- 19.AC (Air Conditioning - IHKA)