

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:lukas@boschgezina.co.za

Sn:988579800333

Time:2024-07-04 07:11:33

Technician Name:bote

Order no:

Service fee:

Notes:

Vehicle Information

Year:2019

Make:HYUNDAI

Model:Grand i10/Xcent(BA)

VIN:MALA851AMKM943923

Displacement:G 1.0 MPI

Odometer:118216 miles

Vehicle Software Version:V10.30

Inspection Result

ECM (Engine Control Module) 1 problems exist

1.U1112 LIN Communication Error

Pending

The following systems are OK:

1.TCM (Transmission Control Module)

2.ABS (Anti-lock Braking System)

3.Airbag(Event #1)

4.Airbag(Event #2)

5.IC (Cluster Module)

6.MDPS (Motor Driven Power Steering)

7.IMMO (Immobilizer)