

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:

Address:

Telephone:N/A

Sn:988579800333

Time:02/17/2025 07:32:02

Technician Name:dries

Vehicle Information

Year:2019

Make:HYUNDAI

Model:Kona(OS)

VIN:KMHK381AMKU191433

Displacement:G 2.0 MPI

Odometer:115831 km

Vehicle Software Version:V10.44

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.TCM (Transmission Control Module)
- 3.ABS (Anti-lock Braking System)
- 4.Airbag(Event #1)
- 5.Airbag(Event #2)
- 6.IBU-TPMS
- 7.IBU-BCM
- 8.IC (Cluster Module)
- 9.MDPS (Motor Driven Power Steering)
- 10.BCW (Blind-Spot Collision Warning)
- 11.Blind-Spot Collision Warning(Ironman)
- 12.RVM (Rear View Monitor)
- 13.IMMO (Immobilizer)
- 14.Integrated Gateway Power Module
- 15.CODE (Transmitter Code Saving)