

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 16758

| Make | ΤΟΥΟΤΑ | |
|-----------------------|-----------------|--------|
| Model | AGYA 1.0 | |
| Vin | MHKA4DA5N0J0001 | 20 |
| Engine Specifications | 1.0 | Petrol |
| Vehicle Type | H/B | |
| Service Plan | N/A | |

| Year | 2021 |
|---------------|-------------------|
| Km | 75564 |
| Transmission | Manual |
| Colour | RED |
| Branch | Bosch Car Service |
| Warranty Plan | N/A |

| Interior | | | | | |
|-----------------------|----------------------|---|------------------|----------------------|---|
| Radio / Entertainment | Within Specification | - | Aircon Controls | Within Specification | • |
| Cluster | Within Specification | - | Electric Windows | Within Specification | - |
| | | | | | |

| Exterior | | | | | |
|-------------------------|----------------------|---|--------------|----------------------|---|
| Windscreen | Within Specification | • | Mag Wheels | Within Specification | - |
| Side Mirrors / Electric | Within Specification | • | Wiper Blades | Within Specification | - |

BOSCH VEHICLE INSPECTION

| Oil Service | | Km | Dip Stick | Within Specification |
|--------------------|----------------------|----|---------------------|----------------------|
| Oil Filter | Within Specification | • | Oil Filler Cap | Within Specification |
| Fuel/Diesel Filter | Within Specification | • | Fan Belt | Within Specification |
| Air Filter | Within Specification | • | Fan belt Tensioner | Within Specification |
| Cabin Filter | Within Specification | • | Alternator Belt | Within Specification |
| Spark Plugs | Within Specification | - | Power Steering Belt | Within Specification |
| Brake Fluid | Within Specification | • | Aircon Belt | Within Specification |
| Antifreeze | Within Specification | • | Multi V belt | Within Specification |
| Rear Main Seal | Within Specification | - | Engine Mountings | Within Specification |
| Sump/Gasket | Within Specification | • | PCV Valve | Within Specification |



| Braking System | | |
|--------------------|----------------------|---|
| Front Brake Pads | 80% | • |
| Front Brake Discs | Within Specification | • |
| Front Brake Sensor | Within Specification | • |
| Rear Brake Pads | 80% | • |
| Rear Brake Discs | Within Specification | • |
| Rear Brake Sensor | Within Specification | • |
| Rear Drums | Within Specification | • |
| Rear Linings | 80% | • |
| Brake Master | Within Specification | • |
| Hand Brake | Within Specification | • |
| Brake Calipers | Within Specification | • |
| Brake Hose | Within Specification | • |

| Cooling System | | |
|-------------------|----------------------|---|
| Radiator | Within Specification | - |
| Radiator Hoses | Within Specification | - |
| Waterpump | Within Specification | - |
| Thermostat | Within Specification | - |
| Aircon Gas | Within Specification | - |
| Aircon Pump | Within Specification | - |
| Aircon Condensor | Within Specification | - |
| Interior Fan | Within Specification | - |
| Interior Radiator | Within Specification | - |

| Fueling System | | |
|-----------------|----------------------|---|
| Intake Manifold | Within Specification | • |
| Throttle | Within Specification | • |
| Turbo | Within Specification | • |
| Injectors | Within Specification | • |
| Fuel Pump | Within Specification | • |
| Fuel Lines | Within Specification | • |

| Ignition System | | |
|-----------------|----------------------|---|
| Ignition Coils | Within Specification | • |
| Glow Plugs | Not Applicable | • |
| Distrubutor | Not Applicable | - |
| HT Leads | Not Applicable | • |



BOSCH INSPECTION REPORT

| Steering & Suspension | | |
|-----------------------|----------------------|---------------------|
| Steering Rack | Within Specification | • |
| Power Steering Pump | Within Specification | • |
| Wheel Alignment | Within Specification | • |
| CV Joints | Within Specification | • |
| CV Boots | Within Specification | • |
| Shocks Front | Within Specification | • |
| Shock Mountings Front | Within Specification | • |
| Shocks Rear | Within Specification | • |
| Stabilizer Links | Within Specification | • |
| Wheel Bearings | Within Specification | ▼ |
| Bearing Hubs | Within Specification | • |
| Control Arms | Within Specification | • |
| Sideshafts/Seal | Within Specification | • |
| Propshaft | Not Applicable | • |
| Wheel Nuts/Studs | Within Specification | - |
| Tyres & Spare | Within Specification | • |
| Mag Wheels/Hub Caps | Within Specification | - |

| Transmission & Clutch | | |
|-----------------------|----------------------|---|
| Clutch Kit | Within Specification | • |
| Clutch Master | Within Specification | • |
| Clutch Slave | Not Applicable | • |
| Clutch Cable | Within Specification | • |
| Gearbox | Within Specification | • |
| Gear & Diff oil | Within Specification | • |
| Auto Transmission | Not Applicable | • |
| Gear Selector | Within Specification | • |
| Gear Linkages | Within Specification | • |

| Ignition System | | |
|------------------|----------------------|---|
| Diagnostics | Within Specification | - |
| Cyl Leakage Test | Within Specification | - |
| Road Test | Within Specification | • |
| Handling | Within Specification | • |

Concluding Remarks

Bosch Technician

Ricardo Myburgh

NEW Technician

General Comments

Date of Inspection

29-Oct-2024



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

