

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:pieter@boschgezina.co.za

Sn:988579800333

Time:10/29/2024 09:29:47

Technician Name:Ricardo

## Vehicle Information

Make:TOYOTA

Model:Agya

VIN:MHKA4DA5N0J000120

Odometer:75568 km

Vehicle Software Version:V10.48

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.EFI (Electronic Fuel Injection)
- 3.EPS (Electric Power Steering)
- 4.SRS (Supplemental Inflatable Restraint System)
- 5.CM (Combination Meter)
- 6.BCM (Body Control Module)
- 7.CSW (Combination Switch)