

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:2024-07-25 12:29:30

Technician Name:Wimpie F

Order no:

Service fee:

Notes:

Vehicle Information

Year:2018

Make:HONDA

Model:JAZZ

VIN:MAK GK58D0J4000269

Odometer:58196 km

Vehicle Software Version:V10.34

Inspection Result

The following systems are OK:

- 1.PGM-FI/Diesel(Engine System)
- 2.AT(Automatic Transmission)
- 3.ABS(Anti-Lock Braking System)
- 4.SRS(Supplemental Inflatable Restraint System)
- 5.EPS(Electric Power Steering)
- 6.Gauge System
- 7.BCM(Body Electrical System)
- 8.Air Conditioning System
- 9.Immobilizer