

# Diagnostic Report

THINKCAR

Time: 11/11/2024 14:17:23

Customer Name: N/A

Technician Name: mike

Shop Name: Bosch Gezina	Telephone: N/A
Email: karika@bosch	Country: South Africa
State: Gauteng	City: Pretoria
Address1: N/A	Address2: N/A

Make: HONDA	Model: BRIO
Year: 2019	Displacement: G 1.2 MPI KAPPA PE
VIN: MAKDG1840K4000058	Odometer: 81008 km
License #: N/A	Vehicle Software Version: V10.42

## Pre-Scan

11/11/2024 14:17:23

System(7)	Status
PGM-FI/Diesel(Engine System)	No Fault
AT(Automatic Transmission)	No Fault
ABS(Anti-Lock Braking System)	No Fault
SRS(Supplemental Inflatable Restraint System)	No Fault
EPS(Electric Power Steering)	No Fault
Gauge System	No Fault
Immobilizer	No Fault