

Year	2021
Km	48212
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	No Fault Code	•	Aircon Controls	Within Specification	•
Cluster	No Fault Code	•	Electric Windows	No Fault Code	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	—
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	No Visible Leaks	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Not Applicable	•	Fan Belt	Not Applicable	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	•	Alternator Belt	No Cracks	•
Spark Plugs	No Fault Code	•	Power Steering Belt	Not Applicable	•
Brake Fluid	No Visible Leaks	•	Aircon Belt	No Cracks	•
Antifreeze	No Visible Leaks	\	Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks	—	Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	80%	
Brake Master	No Visible Leaks	•
Hand Brake	Within Specification	•
Brake Calipers	No Visible Leaks	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	No Visible Leaks	•
Aircon Gas	No Visible Leaks	•
Aircon Pump	No Fault Code	•
Aircon Condensor	No Visible Leaks	•
Interior Fan	No Fault Code	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	No Visible Leaks	-
Throttle	No Fault Code	•
Turbo	No Fault Code	•
Injectors	No Fault Code	•
Fuel Pump	No Fault Code	•
Fuel Lines	No Visible Leaks	-

Ignition System		
Ignition Coils	No Fault Code	•
Glow Plugs	Not Applicable	lacksquare
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	lacksquare



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	~
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	
CV Joints	No Visible Leaks	•
CV Boots	No Visible Leaks	•
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Within Specification	•
Shocks Rear	No Visible Leaks	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	-
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Not Applicable	-
Clutch Master	Not Applicable	
Clutch Slave	Not Applicable	
Clutch Cable	Not Applicable	•
Gearbox	No Visible Leaks	
Gear & Diff oil	No Visible Leaks	
Auto Transmission	Within Specification	
Gear Selector	Within Specification	
Gear Linkages	Within Specification	V

Ignition System		
Diagnostics	No Fault Code	-
Cyl Leakage Test	No Visible Leaks	-
Road Test	Within Specification	-
Handling	Within Specification	-

Concluding Remarks	
Bosch Technician	General Comments
Dries Olwagen	
NEW Technician	Date of Inspection



