Make	NISSAN	
Model	NAVARA 2.3D LE 4X4 A/T P/U D/C	
Vin	MNTCB4D23Z0002155	
Engine Specifications	2.3	Diesel
Vehicle Type	D/C	
Service Plan	N/A	

Year	2018
Km	211226
Transmission	Automatic
Colour	RED
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	lacksquare	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		211226 Km	Dip Stick	Good Condition	V
Oil Filter	Renewed	—	Oil Filler Cap	Good Condition	•
Fuel/Diesel Filter	Good Condition	lacksquare	Fan Belt	Good Condition	•
Air Filter	Good Condition	—	Fan belt Tensioner	Good Condition	•
Cabin Filter	Good Condition		Alternator Belt	Good Condition	•
Spark Plugs	Not Applicable	lacksquare	Power Steering Belt	Good Condition	•
Brake Fluid	Good Condition	—	Aircon Belt	Good Condition	•
Antifreeze	Good Condition	lacksquare	Multi V belt	Good Condition	•
Rear Main Seal	Good Condition	—	Engine Mountings	Good Condition	V
Sump/Gasket	Good Condition	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	80%	—
Front Brake Discs	Good Condition	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	—
Rear Brake Discs	Not Applicable	—
Rear Brake Sensor	Not Applicable	T
Rear Drums	Good Condition	•
Rear Linings	100%	—
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	—
Brake Hose	Good Condition	—

Cooling System		
Radiator	Good Condition	
Radiator Hoses	Good Condition	•
Waterpump	Good Condition	~
Thermostat	Good Condition	
Aircon Gas	Good Condition	•
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	lacksquare
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	—
Throttle	Good Condition	lacksquare
Turbo	Good Condition	lacksquare
Injectors	Good Condition	lacksquare
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Not Applicable	•
Glow Plugs	Good Condition	•
Distrubutor	Not Applicable	•
HT Leads	Not Applicable	—



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Good Condition	•
Power Steering Pump	Good Condition	•
Wheel Alignment	Good Condition	—
CV Joints	Good Condition	V
CV Boots	Good Condition	—
Shocks Front	Good Condition	T
Shock Mountings Front	Good Condition	—
Shocks Rear	Good Condition	—
Stabilizer Links	Good Condition	T
Wheel Bearings	Good Condition	T
Bearing Hubs	Good Condition	•
Control Arms	Good Condition	\
Sideshafts/Seal	Good Condition	T
Propshaft	Good Condition	V
Wheel Nuts/Studs	Good Condition	T
Tyres & Spare	Good Condition	—
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Good Condition	•
Gear Selector	Good Condition	•
Gear Linkages	Good Condition	T

Ignition System		
Diagnostics	Good Condition	
Cyl Leakage Test	Good Condition	_
Road Test	Good Condition	-
Handling	Good Condition	~

Concluding Remarks	
Bosch Technician	General Comments
-Select-	
NEW Technician	Date of Inspection



