

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Email:juan-dre@boschgezina.co.za
Sn:988579800333
Time:11/19/2024 13:03:33
Technician Name:wimpie

Vehicle Information

Year:2019
Make:HONDA
Model:BRIO
VIN:MAKDG1840K4000303
Odometer:63001 km
Vehicle Software Version:V10.44

Inspection Result

The following systems are OK:

- 1.PGM-FI/Diesel(Engine System)
- 2.AT(Automatic Transmission)
- 3.ABS(Anti-Lock Braking System)
- 4.SRS(Supplemental Inflatable Restraint System)
- 5.EPS(Electric Power Steering)
- 6.Gauge System
- 7.BCM(Body Electrical System)
- 8.Air Conditioning System
- 9.Immobilizer
- 10.PSR(Parking Sensor)