

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: karika@boschgezina.co.za

Sn: 988579800333

Time: 2024-08-03 10:49:01

Technician Name: Mike Jones

Order no:

Service fee:

Notes:

## Vehicle Information

Make: TOYOTA

Model: Agya

VIN: MHKA4DA5N0J000367

Odometer: 70296 km

Vehicle Software Version: V10.44

## Inspection Result

The following systems are OK:

1. EOBD/OBD II
2. EFI (Electronic Fuel Injection)
3. EPS (Electric Power Steering)
4. SRS (Supplemental Inflatable Restraint System)
5. CM (Combination Meter)
6. BCM (Body Control Module)
7. CSW (Combination Switch)