

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:2024-09-06 16:17:29

Technician Name:Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Year:2016

Make:OPEL

Model:Adam

VIN:W0L0MAP08G6003878

Odometer:0130312 km

Vehicle Software Version:V10.48

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.CCM (Chassis Control Module)
- 3.EBCM (Electronic Brake Control Module)
- 4.PSCM (Power Steering Control Module)
- 5.BCM (Body Control Module)
- 6.SRS (Inflatable Restraint Sensing And Diagnostic Module)
- 7.IC (Instrument Cluster)
- 8.RADIO (Radio)
- 9.PACM (Parking Assist Control Module)