

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: johan@boschgezina.co.za

Sn: 988579800333

Time: 2024-10-17 09:50:59

Technician Name: Eugene

Order no:

Service fee:

Notes:

## Vehicle Information

Year: 2019

Make: HONDA

Model: BRIO AMAZE

VIN: MAKDF5630K4000476

Odometer: 91377 km

Vehicle Software Version: V10.34

## Inspection Result

The following systems are OK:

1. PGM-FI/Diesel (Engine System)
2. AT (Automatic Transmission)
3. ABS (Anti-Lock Braking System)
4. SRS (Supplemental Inflatable Restraint System)
5. EPS (Electric Power Steering)
6. Gauge System
7. BCM (Body Electrical System)
8. Air Conditioning System
9. Immobilizer