

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:
Address:
Telephone:N/A
Sn:988579800333
Time:01/07/2025 11:24:34
Technician Name:wimpie

Vehicle Information

Make:RENAULT
Model:CAPTUR/QM3/KABIN
VIN:VF12R5A1H52800532
Displacement:G 1.2 MPI KAPPA
Odometer:121229 km
Vehicle Software Version:V10.40

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.UCH
- 3.ABS (Anti-lock Braking System)
- 4.IC (Instrument Cluster)
- 5.AC (Air Conditioning)
- 6.SRS (Supplemental Inflatable Restraint System)
- 7.Parking Prox Can
- 8.Radio
- 9.Variable P.A.S
- 10.UPC
- 11.Hands-Free Module