Make	ТОУОТА	
Model	COROLLA CROSS 1.8 XI	
Vin	AHTKFAAG80060102	23
Engine Specifications	1.8	Petrol
Vehicle Type	SUV	
Service Plan	N/A	

Year	2021
Km	84411
Transmission	Automatic
Colour	BLACK
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	<b>—</b>	Aircon Controls	Within Specification	_
Cluster	Within Specification	V	Electric Windows	Within Specification	V

Exterior					
Windscreen	Within Specification	-	Mag Wheels	Within Specification	<b>~</b>
Side Mirrors / Electric	Within Specification	<b>—</b>	Wiper Blades	Renewed	<b>~</b>

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		Km	Dip Stick	Within Specification	•
Oil Filter	Renewed	•	Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Not Applicable	•
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification	<b>~</b>	Alternator Belt	Not Applicable	•
Spark Plugs	Within Specification	•	Power Steering Belt	Not Applicable	•
Brake Fluid	Within Specification	<b>~</b>	Aircon Belt	Not Applicable	•
Antifreeze	Within Specification	•	Multi V belt	No Cracks	•
Rear Main Seal	Within Specification	•	Engine Mountings	Within Specification	•
Sump/Gasket	Within Specification	•	PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	<b>—</b>
Rear Brake Pads	60%	•
Rear Brake Discs	Within Specification	<b>—</b>
Rear Brake Sensor	Not Applicable	<b>T</b>
Rear Drums	Not Applicable	•
Rear Linings	-Select-	<b>—</b>
Brake Master	Within Specification	•
Hand Brake	Within Specification	<b>—</b>
Brake Calipers	Within Specification	<b>—</b>
Brake Hose	Within Specification	<b>—</b>

Cooling System		
Radiator	Within Specification	<b>—</b>
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	_
Thermostat	Within Specification	•
Aircon Gas	Within Specification	<b>\rightarrow</b>
Aircon Pump	Within Specification	<b>—</b>
Aircon Condensor	Within Specification	<b>V</b>
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	_
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	-

Ignition System		
Ignition Coils	Within Specification	<b>—</b>
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>—</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	<b>—</b>
Power Steering Pump	Within Specification	<b>—</b>
Wheel Alignment	Within Specification	<b>—</b>
CV Joints	Within Specification	<b>V</b>
CV Boots	Within Specification	
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	<b>•</b>
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	<b>—</b>
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	<b>\</b>
Clutch Cable	Within Specification	<b>T</b>
Gearbox	Within Specification	<b>T</b>
Gear & Diff oil	Within Specification	<b>—</b>
Auto Transmission	Within Specification	<b>—</b>
Gear Selector	Within Specification	<b>V</b>
Gear Linkages	Within Specification	<b>V</b>

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	-
Handling	Within Specification	•

Concluding Remarks		

Bosch Technician	General Comments
Eugene J.v. Rensburg	
NEW Technician	Date of Inspection
	25-Sep-2024



