

Diagnostic Report

THINKCAR

Time: 09/25/2024 07:43:17

Customer Name: N/A

Technician Name: Eugene

Shop Name: N/A	Telephone: N/A
Email: pieter	Country: N/A
State: N/A	City: N/A
Address1: N/A	Address2: N/A

Make: TOYOTA	Model: Corolla Cross
Year: 2020	Displacement: G 2.0 MPI
VIN: AHTKFAAG800601023	Odometer: 84628 km
License #: N/A	Vehicle Software Version: V10.44

Pre-Scan

09/25/2024 07:43:17

System(19)	Status
EOBD/OBD II	No Fault
ECMECT (Engine and ECT)	No Fault
CCS (Cruise Control)	No Fault
ABS (Brake Control)	No Fault
EMPS (Electronic Motor Power Steering)	No Fault
SAS (Steering Angle Sensor)	No Fault
SRS (Supplemental Inflatable Restraint System)	No Fault
AC (Air Conditioning)	No Fault
CM (Combination Meter)	No Fault
BCM (Body Control Module)	No Fault

ES (Entry&Start)	No Fault
CGW (Central Gateway)	No Fault
DDM (Driver Door Motor)	No Fault
PDM (Passenger Door Motor)	No Fault
RLDM (Rear Left Door Motor)	No Fault
RRDM (Rear Right Door Motor)	No Fault
MSW (Master Switch)	No Fault
PSC (Power Source Control)	No Fault
SC (Starting Control)	No Fault