

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:jaco@boschgezina.co.za

Sn:988579800333

Time:2024-05-30 13:04:47

Technician Name:Raymond

Order no:

Service fee:

Notes:

## Vehicle Information

Year:2019.09-

Make:TOYOTA

Model:Corolla

VIN:JTNKY3BE503001411

Displacement:G 2.0 MPI NU

Odometer:79547.00 km

Vehicle Software Version:V10.44

## Inspection Result

The following systems are OK:

- 1.EOBD/OBD II
- 2.ECM (Engine Control Module)
- 3.CCS (Cruise Control)
- 4.TCM (Transmission Control Module)
- 5.ABS (Brake Control)/EPB (Electrical Parking Brake)
- 6.SAS (Steering Angle Sensor)
- 7.SRS (Supplemental Inflatable Restraint System)
- 8.AC (Air Conditioning)
- 9.CM (Combination Meter)
- 10.SC (Starting Control)
- 11.NS (Navigation System)
- 12.BCM (Body Control Module)
- 13.ES (Entry&Start)
- 14.CGW (Central Gateway)
- 15.DDM (Driver Door Motor)
- 16.PDM (Passenger Door Motor)
- 17.RLDM (Rear Left Door Motor)
- 18.RRDM (Rear Right Door Motor)
- 19.MSW (Master Switch)
- 20.PSC (Power Source Control)