Make	RENAULT	
Model	KWID 1.0 DYNAMIQUE 5DR	
Vin	MEEBBA0000070187	3
Engine Specifications	1.0	Petrol
Vehicle Type	H/B	
Service Plan	N/A	

Year	2020
Km	50053
Transmission	Manual
Colour	BLUE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Good Condition	-	Aircon Controls	Good Condition	•
Cluster	Good Condition	•	Electric Windows	Good Condition	•

Exterior					
Windscreen	Good Condition		Mag Wheels	Renewed	•
Side Mirrors / Electric	Not Applicable	-	Wiper Blades	Renewed	<b>—</b>

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service		50053 Km	Dip Stick	No Visible Leaks	•
Oil Filter	Renewed	_	Oil Filler Cap	No Visible Leaks	<b>~</b>
Fuel/Diesel Filter	Within Specification	<b>—</b>	Fan Belt	No Cracks	<b>T</b>
Air Filter	Within Specification	_	Fan belt Tensioner	Good Condition	•
Cabin Filter	Within Specification	-	Alternator Belt	No Cracks	•
Spark Plugs	Within Specification	<b>—</b>	Power Steering Belt	No Cracks	-
Brake Fluid	Within Specification	-	Aircon Belt	No Cracks	•
Antifreeze	Within Specification	•	Multi V belt	No Cracks	<b>T</b>
Rear Main Seal	Within Specification	-	Engine Mountings	Good Condition	•
Sump/Gasket	No Visible Leaks	•	PCV Valve	Good Condition	•

Braking System		
Front Brake Pads	60%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Not Applicable	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Within Specification	•
Rear Linings	60%	•
Brake Master	Good Condition	•
Hand Brake	Good Condition	•
Brake Calipers	Good Condition	•
Brake Hose	Good Condition	•

Cooling System		
Radiator	No Visible Leaks	
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	-
Thermostat	No Visible Leaks	
Aircon Gas	Good Condition	
Aircon Pump	Good Condition	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	Good Condition	•

Fueling System		
Intake Manifold	Good Condition	•
Throttle	Good Condition	•
Turbo	Not Applicable	•
Injectors	Good Condition	•
Fuel Pump	Good Condition	•
Fuel Lines	Good Condition	•

Ignition System		
Ignition Coils	Good Condition	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	<b>V</b>



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Good Condition	-
Power Steering Pump	Good Condition	
Wheel Alignment	Renewed	
CV Joints	Good Condition	
CV Boots	No Visible Leaks	lacksquare
Shocks Front	No Visible Leaks	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	
Wheel Bearings	Good Condition	
Bearing Hubs	Good Condition	lacksquare
Control Arms	Good Condition	
Sideshafts/Seal	Good Condition	
Propshaft	Not Applicable	
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Renewed	
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Good Condition	-
Clutch Master	Good Condition	-
Clutch Slave	Good Condition	•
Clutch Cable	Not Applicable	-
Gearbox	Good Condition	-
Gear & Diff oil	Good Condition	-
Auto Transmission	Not Applicable	-
Gear Selector	Good Condition	<b>~</b>
Gear Linkages	Good Condition	<b>V</b>

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	Good Condition	_
Road Test	Good Condition	-
Handling	Good Condition	<b>~</b>

Concluding Remarks			

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
HENDRIE	17-Sep-2024



