

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:karika@boschgezina.co.za

Sn:988579800333

Time:11/11/2024 13:45:35

Technician Name:Elias

Vehicle Information

Make:NISSAN

VIN:MNTCB4D23Z0002155

Displacement:G 1.4 DOHC

Odometer:217288 km

Vehicle Software Version:V10.46

Inspection Result

The following systems are OK:

- 1.ECM (Engine Control Module)
- 2.Anti-lock Brake System(ABS)
- 3.Instrument cluster
- 4.Body Control System(BCM)
- 5.Supplemental Restraint System(SRS)
- 6.Heating, Ventilation & Air Conditioning system(HVAC)
- 7.Intelligent Power Distribution Unit(IPDU)
- 8.Headlamp Leveling System(HLL)
- 9.All Wheel Drive(AWD)/4 Wheel Drive(4WD) system
- 10.Parking Distance Control(SONAR)