Make	NISSAN	
Model	X TRAIL 2.5 ACENTA 4X4 CVT	
Vin	JN1JBNT32Z0102159	
Engine Specifications	2.5 Pe	etrol
Vehicle Type	SUV	
Service Plan	N/A	

Year	2022
Km	91348
Transmission	Automatic
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	<b>-</b>	Aircon Controls	Good Condition	<b>~</b>
Cluster	Within Specification	•	Electric Windows	Good Condition	<b>—</b>

Exterior					
Windscreen	Good Condition	-	Mag Wheels	Good Condition	•
Side Mirrors / Electric	Good Condition	<b>—</b>	Wiper Blades	Good Condition	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Within Specification		Oil Filler Cap	No Visible Leaks	•
Fuel/Diesel Filter	Within Specification		Fan Belt	Good Condition	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	Good Condition	•
Spark Plugs	Within Specification		Power Steering Belt	Not Applicable	-
Brake Fluid	Good Condition		Aircon Belt	Good Condition	-
Antifreeze	Good Condition		Multi V belt	Good Condition	•
Rear Main Seal	No Visible Leaks		Engine Mountings	Good Condition	-
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	lacksquare
Front Brake Sensor	Not Applicable	•
Rear Brake Pads	-Select-	lacksquare
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Not Applicable	•
Rear Drums	Not Applicable	•
Rear Linings	-Select-	•
Brake Master	Good Condition	•
Hand Brake	Within Specification	•
Brake Calipers	Good Condition	•
Brake Hose	No Visible Leaks	•

Cooling System		
Radiator	Within Specification	-
Radiator Hoses	No Visible Leaks	•
Waterpump	Within Specification	-
Thermostat	Within Specification	-
Aircon Gas	Good Condition	•
Aircon Pump	Within Specification	•
Aircon Condensor	Good Condition	•
Interior Fan	Good Condition	•
Interior Radiator	No Visible Leaks	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Not Applicable	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	<b>~</b>
Fuel Lines	No Visible Leaks	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	<b>—</b>
Power Steering Pump	Not Applicable	•
Wheel Alignment	Within Specification	•
CV Joints	Good Condition	•
CV Boots	No Visible Leaks	•
Shocks Front	Good Condition	•
Shock Mountings Front	Good Condition	•
Shocks Rear	Good Condition	lacksquare
Stabilizer Links	Good Condition	<b>V</b>
Wheel Bearings	Good Condition	•
Bearing Hubs	Within Specification	lacksquare
Control Arms	Good Condition	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Within Specification	
Wheel Nuts/Studs	Good Condition	•
Tyres & Spare	Good Condition	lacksquare
Mag Wheels/Hub Caps	Good Condition	•

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	-
Clutch Slave	Not Applicable	•
Clutch Cable	Not Applicable	•
Gearbox	Not Applicable	-
Gear & Diff oil	Within Specification	-
Auto Transmission	Within Specification	
Gear Selector	Within Specification	-
Gear Linkages	Within Specification	<b>V</b>

Ignition System		
Diagnostics	No Fault Code	
Cyl Leakage Test	No Visible Leaks	_
Road Test	Good Condition	_
Handling	Good Condition	-

Concluding Remarks			

Bosch Technician	General Comments
-Select-	

NEW Technician	Date of Inspection
RIAAN MEINTJIES	12-Sep-2024



