

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:juan-dre@boschgezina.co

Sn:988579800333

Time:2024-07-16 14:05:26

Technician Name:Raymond

Order no:

Service fee:

Notes:

Vehicle Information

Year:2013

Make:VW

VIN:WVWZZZ16ZDM024749

Odometer:119760 km

Vehicle Software Version:V10.23

Inspection Result

The following systems are OK:

1.01 Engine Electronics

2.03 Brake Electronics

3.08 Climate Control Module

4.09 Electronic Central Electric

5.15 Airbag

6.16 Steering Column Electronics Systems

7.17 Instrument Cluster

8.19 Data Bus OBD Interface

9.25 Anti-Theft Immobilizer

10.42 Driver's Door Electronics

11.44 Power Steering

12.52 Passenger's Door Electronics

13.56 Radio

14.77 Telephone