

Engine

BOSCH INSPECTION REPORT

JOB CARD NUMBER 14787

Make	AUDI	
Model	Q3 1.4T FSI (110KW)	
Vin	WAUZZZ8U4FR03591	2
Engine Specifications	1.4	Petrol 🔽
Vehicle Type	SUV	
Service Plan	N/A	

Year	2015
Km	88056
Transmission	Manual
Colour	WHITE
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	-	Aircon Controls	Within Specification	•
Cluster	Within Specification	-	Electric Windows	Within Specification	-

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Within Specification	-
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Within Specification	-

BOSCH VEHICLE INSPECTION

Oil Service		88060 Km	Dip Stick	Within Specification
Oil Filter	Within Specification	•	Oil Filler Cap	Within Specification
Fuel/Diesel Filter	Within Specification	•	Fan Belt	Within Specification
Air Filter	Within Specification	•	Fan belt Tensioner	Within Specification
Cabin Filter	Within Specification	•	Alternator Belt	Within Specification
Spark Plugs	Within Specification	•	Power Steering Belt	Within Specification
Brake Fluid	Within Specification	•	Aircon Belt	Within Specification
Antifreeze	Within Specification	~	Multi V belt	Within Specification
Rear Main Seal	No Visible Leaks	•	Engine Mountings	Within Specification
Sump/Gasket	No Visible Leaks	•	PCV Valve	Within Specification



Braking System		
Front Brake Pads	-Select-	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	-Select-	•
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	•
Rear Drums	Not Applicable	-
Rear Linings	-Select-	•
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	•
Brake Hose	Within Specification	•

Cooling System		
Radiator	Within Specification	•
Radiator Hoses	Within Specification	•
Waterpump	Within Specification	•
Thermostat	Within Specification	•
Aircon Gas	Within Specification	•
Aircon Pump	Within Specification	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	Within Specification	•

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	-
Turbo	Within Specification	-
Injectors	Within Specification	•
Fuel Pump	Within Specification	•
Fuel Lines	Within Specification	•

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	-
HT Leads	Not Applicable	-



BOSCH INSPECTION REPORT

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	•
Wheel Alignment	Within Specification	•
CV Joints	Within Specification	•
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	•
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	Within Specification	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	•
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	•

Transmission & Clutch		
Clutch Kit	Within Specification	•
Clutch Master	Within Specification	•
Clutch Slave	Within Specification	•
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	No Visible Leaks	•
Auto Transmission	Not Applicable	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	•

Ignition System		
Diagnostics	Within Specification	-
Cyl Leakage Test	Within Specification	-
Road Test	Within Specification	•
Handling	Within Specification	•

Concluding Remarks

Bosch Technician

-Select-

General Comments

Date of Inspection



BOSCH

Service

NEW Technician



BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

