

All System Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:bosch service centre

Address:564 Steve Biko Road

Telephone:0123355737

Email:lukas@boschgezina.co.za

Sn:988579800333

Time:2024-07-23 13:32:07

Technician Name:Lesego

Order no:

Service fee:

Notes:

Vehicle Information

Make:AUDI

VIN:WAUZZZ8U4FR035912

Displacement:G 1.0 MPI KAPPA

Odometer:88060 km

Vehicle Software Version:V10.26

Inspection Result

The following systems are OK:

1.01 Engine Electronics

2.03 Brake Electronics

3.08 Climate Control Module

4.09 Electronic Central Electric

5.15 Airbag

6.16 Steering Column Electronics Systems

7.17 Instrument Cluster

8.19 Data Bus OBD Interface

9.25 Anti-Theft Immobilizer

10.42 Driver's Door Electronics

11.44 Power Steering

12.52 Passenger's Door Electronics

13.55 Headlamp Range Control

14.5F Information Electronics 1

15.62 Left Rear Door Electronics

16.72 Right Rear Door Electronics