

Engine

# **BOSCH INSPECTION REPORT**

JOB CARD NUMBER 14163

| Make                  | INFINITI         |        |
|-----------------------|------------------|--------|
| Model                 | Q50 2.2D PREMIUM | A/T    |
| Vin                   | JN1BDAV37U020371 | 6      |
| Engine Specifications | 2.2              | Diesel |
| Vehicle Type          | S/D              |        |
| Service Plan          | N/A              |        |

| Year          | 2016              |
|---------------|-------------------|
| Km            | 82244             |
| Transmission  | Automatic         |
| Colour        | GREEN             |
| Branch        | Bosch Car Service |
| Warranty Plan | N/A               |

| Interior              |                      |   |                  |                      |   |
|-----------------------|----------------------|---|------------------|----------------------|---|
| Radio / Entertainment | Within Specification | - | Aircon Controls  | Within Specification | • |
| Cluster               | Within Specification | - | Electric Windows | Within Specification | • |
|                       |                      |   |                  |                      |   |

| Exterior                |                      |   |              |                      |   |
|-------------------------|----------------------|---|--------------|----------------------|---|
| Windscreen              | Within Specification | • | Mag Wheels   | Within Specification | - |
| Side Mirrors / Electric | Within Specification | • | Wiper Blades | Within Specification | - |

## **BOSCH VEHICLE INSPECTION**

| Oil Service        | SERVICE DUE Km       | Dip Stick           | Within Specification | · |
|--------------------|----------------------|---------------------|----------------------|---|
| Oil Filter         | Within Specification | Oil Filler Cap      | Within Specification | · |
| Fuel/Diesel Filter | Within Specification | Fan Belt            | Not Applicable       |   |
| Air Filter         | Within Specification | Fan belt Tensioner  | Within Specification | · |
| Cabin Filter       | Within Specification | Alternator Belt     | Not Applicable       |   |
| Spark Plugs        | Not Applicable       | Power Steering Belt | Not Applicable       | · |
| Brake Fluid        | Within Specification | Aircon Belt         | Not Applicable       | · |
| Antifreeze         | Within Specification | Multi V belt        | Within Specification | · |
| Rear Main Seal     | Within Specification | Engine Mountings    | Within Specification |   |
| Sump/Gasket        | Within Specification | PCV Valve           | Within Specification | · |

# BOSCH INSPECTION REPORT

| Braking System     |                      |   |
|--------------------|----------------------|---|
| Front Brake Pads   | 100%                 | • |
| Front Brake Discs  | Within Specification | • |
| Front Brake Sensor | Not Applicable       | • |
| Rear Brake Pads    | 100%                 | • |
| Rear Brake Discs   | Within Specification | • |
| Rear Brake Sensor  | Not Applicable       | • |
| Rear Drums         | Within Specification | • |
| Rear Linings       | 60%                  | • |
| Brake Master       | Within Specification | • |
| Hand Brake         | Within Specification | • |
| Brake Calipers     | Within Specification | • |
| Brake Hose         | Within Specification | • |

| Cooling System    |                      |   |
|-------------------|----------------------|---|
| Radiator          | Within Specification | • |
| Radiator Hoses    | Within Specification | • |
| Waterpump         | Within Specification | • |
| Thermostat        | Within Specification | • |
| Aircon Gas        | Within Specification | • |
| Aircon Pump       | Within Specification | - |
| Aircon Condensor  | Within Specification | - |
| Interior Fan      | Within Specification | • |
| Interior Radiator | Within Specification | - |

| Fueling System  |                      |   |
|-----------------|----------------------|---|
| Intake Manifold | Within Specification | • |
| Throttle        | Within Specification | • |
| Turbo           | Not Applicable       | • |
| Injectors       | Within Specification | • |
| Fuel Pump       | Within Specification | • |
| Fuel Lines      | Within Specification | • |

| Ignition System |                      |   |
|-----------------|----------------------|---|
| Ignition Coils  | Not Applicable       | • |
| Glow Plugs      | Within Specification | • |
| Distrubutor     | Not Applicable       | - |
| HT Leads        | Not Applicable       | - |



## **BOSCH INSPECTION REPORT**

| Steering & Suspension |                      |   |
|-----------------------|----------------------|---|
| Steering Rack         | Within Specification | • |
| Power Steering Pump   | Within Specification | • |
| Wheel Alignment       | Within Specification | • |
| CV Joints             | Within Specification | • |
| CV Boots              | Within Specification | • |
| Shocks Front          | Within Specification | • |
| Shock Mountings Front | Within Specification | • |
| Shocks Rear           | Within Specification | • |
| Stabilizer Links      | Within Specification | • |
| Wheel Bearings        | Within Specification | • |
| Bearing Hubs          | Within Specification | • |
| Control Arms          | Within Specification | - |
| Sideshafts/Seal       | Within Specification | • |
| Propshaft             | Not Applicable       | • |
| Wheel Nuts/Studs      | Within Specification | • |
| Tyres & Spare         | Within Specification | • |
| Mag Wheels/Hub Caps   | Within Specification | • |

| Transmission & Clutch |                      |   |
|-----------------------|----------------------|---|
| Clutch Kit            | Within Specification | • |
| Clutch Master         | Not Applicable       | • |
| Clutch Slave          | Not Applicable       | • |
| Clutch Cable          | Not Applicable       | • |
| Gearbox               | Within Specification | • |
| Gear & Diff oil       | Within Specification | • |
| Auto Transmission     | Within Specification | • |
| Gear Selector         | Within Specification | • |
| Gear Linkages         | Within Specification | • |

| Ignition System  |                      |   |
|------------------|----------------------|---|
| Diagnostics      | Within Specification | • |
| Cyl Leakage Test | Not Applicable       | - |
| Road Test        | Not Applicable       | • |
| Handling         | Not Applicable       | • |

#### **Concluding Remarks**

## Bosch Technician

-Select-

### **General Comments**

MICHAEL JONES

**NEW Technician** 

## Date of Inspection

21-Jun-2024



## BOSCH CAR SERVICE PRETORIA

a: 564 Steve Biko Road, Gezina, Pretoria 0084 t: 012 335 5737 e: reception@boschgezina.co.za

