

# All System Diagnostic Report

The Report is created by **THINKCAR**

## Repair Shop

Shop Name: bosch service centre

Address: 564 Steve Biko Road

Telephone: 0123355737

Email: johan@boschgezina.co.za

Sn: 988579800333

Time: 2024-09-30 13:46:08

Technician Name: Christiaan

Order no:

Service fee:

Notes:

## Vehicle Information

Make: JPISUZU

Model: TF Series (D-MAX)

Displacement: D 2.5 TCI-A2

Odometer: 159609 km

Vehicle Software Version: V10.30

## Inspection Result

The following systems are OK:

1. IBS (Intelligent Battery System)

2. Meter

3. Meter\_1

4. SRS (Denso)

5. TPMS (Tire Pressure Monitoring System)