



Make	OPEL	
Model	ADAM 1.0T JAM (3DR)	
Vin	W0L0MAP08G6003878	
Engine Specifications	1.0	Petrol <input type="checkbox"/>
Vehicle Type	H/B	
Service Plan	N/A	

Year	2015	
Km	130310	
Transmission	Manual	<input type="checkbox"/>
Colour	YELLOW	
Branch	Bosch Car Service	
Warranty Plan	N/A	

Interior

Radio / Entertainment	Working Condition	<input type="checkbox"/>	Aircon Controls	Working Condition	<input type="checkbox"/>
Cluster	Good Condition	<input type="checkbox"/>	Electric Windows	Working Condition	<input type="checkbox"/>

Exterior

Windscreen	Good Condition	<input type="checkbox"/>	Mag Wheels	Good Condition	<input type="checkbox"/>
Side Mirrors / Electric	Within Specification	<input type="checkbox"/>	Wiper Blades	Within Specification	<input type="checkbox"/>

BOSCH VEHICLE INSPECTION

Engine

Oil Service	SERVICE DONE Km		Dip Stick	Good Condition	<input type="checkbox"/>
Oil Filter	Renewed	<input type="checkbox"/>	Oil Filler Cap	No Visible Leaks	<input type="checkbox"/>
Fuel/Diesel Filter	No Visible Leaks	<input type="checkbox"/>	Fan Belt	No Cracks	<input type="checkbox"/>
Air Filter	Within Specification	<input type="checkbox"/>	Fan belt Tensioner	Within Specification	<input type="checkbox"/>
Cabin Filter	Within Specification	<input type="checkbox"/>	Alternator Belt	No Cracks	<input type="checkbox"/>
Spark Plugs	Within Specification	<input type="checkbox"/>	Power Steering Belt	Not Applicable	<input type="checkbox"/>
Brake Fluid	No Visible Leaks	<input type="checkbox"/>	Aircon Belt	No Cracks	<input type="checkbox"/>
Antifreeze	No Visible Leaks	<input type="checkbox"/>	Multi V belt	No Cracks	<input type="checkbox"/>
Rear Main Seal	No Visible Leaks	<input type="checkbox"/>	Engine Mountings	Within Specification	<input type="checkbox"/>
Sump/Gasket	No Visible Leaks	<input type="checkbox"/>	PCV Valve	Within Specification	<input type="checkbox"/>

Braking System		
Front Brake Pads	60%	<input type="checkbox"/>
Front Brake Discs	Within Specification	<input type="checkbox"/>
Front Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Brake Pads	80%	<input type="checkbox"/>
Rear Brake Discs	Within Specification	<input type="checkbox"/>
Rear Brake Sensor	Not Applicable	<input type="checkbox"/>
Rear Drums	Not Applicable	<input type="checkbox"/>
Rear Linings	-Select-	<input type="checkbox"/>
Brake Master	No Visible Leaks	<input type="checkbox"/>
Hand Brake	Within Specification	<input type="checkbox"/>
Brake Calipers	No Visible Leaks	<input type="checkbox"/>
Brake Hose	No Visible Leaks	<input type="checkbox"/>

Cooling System		
Radiator	No Visible Leaks	<input type="checkbox"/>
Radiator Hoses	No Visible Leaks	<input type="checkbox"/>
Waterpump	Within Specification	<input type="checkbox"/>
Thermostat	Within Specification	<input type="checkbox"/>
Aircon Gas	No Visible Leaks	<input type="checkbox"/>
Aircon Pump	Within Specification	<input type="checkbox"/>
Aircon Condensor	No Visible Leaks	<input type="checkbox"/>
Interior Fan	Within Specification	<input type="checkbox"/>
Interior Radiator	No Visible Leaks	<input type="checkbox"/>

Fueling System		
Intake Manifold	Within Specification	<input type="checkbox"/>
Throttle	Within Specification	<input type="checkbox"/>
Turbo	Within Specification	<input type="checkbox"/>
Injectors	Within Specification	<input type="checkbox"/>
Fuel Pump	Within Specification	<input type="checkbox"/>
Fuel Lines	No Visible Leaks	<input type="checkbox"/>

Ignition System		
Ignition Coils	No Fault Code	<input type="checkbox"/>
Glow Plugs	Not Applicable	<input type="checkbox"/>
Distributor	Not Applicable	<input type="checkbox"/>
HT Leads	Not Applicable	<input type="checkbox"/>

Steering & Suspension		
Steering Rack	Within Specification	<input type="checkbox"/>
Power Steering Pump	Not Applicable	<input type="checkbox"/>
Wheel Alignment	Within Specification	<input type="checkbox"/>
CV Joints	Within Specification	<input type="checkbox"/>
CV Boots	No Visible Leaks	<input type="checkbox"/>
Shocks Front	Renewed	<input type="checkbox"/>
Shock Mountings Front	Within Specification	<input type="checkbox"/>
Shocks Rear	No Visible Leaks	<input type="checkbox"/>
Stabilizer Links	Within Specification	<input type="checkbox"/>
Wheel Bearings	Within Specification	<input type="checkbox"/>
Bearing Hubs	Within Specification	<input type="checkbox"/>
Control Arms	Within Specification	<input type="checkbox"/>
Sideshafts/Seal	No Visible Leaks	<input type="checkbox"/>
Propshaft	Not Applicable	<input type="checkbox"/>
Wheel Nuts/Studs	Within Specification	<input type="checkbox"/>
Tyres & Spare	Within Specification	<input type="checkbox"/>
Mag Wheels/Hub Caps	Within Specification	<input type="checkbox"/>

Transmission & Clutch		
Clutch Kit	Within Specification	<input type="checkbox"/>
Clutch Master	No Visible Leaks	<input type="checkbox"/>
Clutch Slave	No Visible Leaks	<input type="checkbox"/>
Clutch Cable	Not Applicable	<input type="checkbox"/>
Gearbox	Within Specification	<input type="checkbox"/>
Gear & Diff oil	No Visible Leaks	<input type="checkbox"/>
Auto Transmission	Not Applicable	<input type="checkbox"/>
Gear Selector	Good Condition	<input type="checkbox"/>
Gear Linkages	Within Specification	<input type="checkbox"/>

Ignition System		
Diagnostics	No Fault Code	<input type="checkbox"/>
Cyl Leakage Test	No Visible Leaks	<input type="checkbox"/>
Road Test	Within Specification	<input type="checkbox"/>
Handling	Within Specification	<input type="checkbox"/>

Concluding Remarks

Bosch Technician

Raymond Mncube

General Comments

NEW Technician

Date of Inspection

04-Sep-2024