Make	FORD		
Model	FIESTA 1.0 ECOBOOST AMBIENTE POWERS		
Vin	WF0DXXGAKDHJ039	69	
Engine Specifications	1.0	Petrol	
Vehicle Type	H/B		
Service Plan	N/A		

Year	2017
Km	53662
Transmission	Automatic
Colour	SILVER
Branch	Bosch Car Service
Warranty Plan	N/A

Interior					
Radio / Entertainment	Within Specification	•	Aircon Controls	Within Specification	<b>~</b>
Cluster	Within Specification	•	Electric Windows	Within Specification	•

Exterior					
Windscreen	Within Specification	•	Mag Wheels	Not Applicable	-
Side Mirrors / Electric	Within Specification	•	Wiper Blades	Not Applicable	•

BOSCH VEHICLE INSPECTION					
Engine					
Oil Service	SERVICE DUE Km		Dip Stick	Within Specification	•
Oil Filter	Renewed		Oil Filler Cap	Within Specification	•
Fuel/Diesel Filter	Within Specification		Fan Belt	No Cracks	•
Air Filter	Within Specification		Fan belt Tensioner	Within Specification	•
Cabin Filter	Within Specification		Alternator Belt	No Cracks	•
Spark Plugs	Within Specification		Power Steering Belt	No Cracks	•
Brake Fluid	Within Specification		Aircon Belt	No Cracks	•
Antifreeze	Within Specification		Multi V belt	No Cracks	•
Rear Main Seal	No Visible Leaks		Engine Mountings	Within Specification	•
Sump/Gasket	No Visible Leaks		PCV Valve	Within Specification	•

Braking System		
Front Brake Pads	100%	•
Front Brake Discs	Within Specification	•
Front Brake Sensor	Within Specification	•
Rear Brake Pads	100%	<b>—</b>
Rear Brake Discs	Within Specification	•
Rear Brake Sensor	Within Specification	<b>T</b>
Rear Drums	Within Specification	•
Rear Linings	100%	<b>—</b>
Brake Master	Within Specification	•
Hand Brake	Within Specification	•
Brake Calipers	Within Specification	<b>—</b>
Brake Hose	Within Specification	<b>—</b>

Cooling System		
Radiator	No Visible Leaks	•
Radiator Hoses	No Visible Leaks	•
Waterpump	No Visible Leaks	•
Thermostat	Within Specification	-
Aircon Gas	Within Specification	•
Aircon Pump	No Visible Leaks	•
Aircon Condensor	Within Specification	•
Interior Fan	Within Specification	•
Interior Radiator	No Visible Leaks	lacksquare

Fueling System		
Intake Manifold	Within Specification	•
Throttle	Within Specification	•
Turbo	Within Specification	•
Injectors	Within Specification	•
Fuel Pump	Within Specification	<b>—</b>
Fuel Lines	Within Specification	<b>—</b>

Ignition System		
Ignition Coils	Within Specification	•
Glow Plugs	Not Applicable	•
Distrubutor	Not Applicable	<b>~</b>
HT Leads	Not Applicable	•



## **BOSCH INSPECTION REPORT**

Steering & Suspension		
Steering Rack	Within Specification	•
Power Steering Pump	Within Specification	
Wheel Alignment	Within Specification	
CV Joints	Within Specification	
CV Boots	Within Specification	•
Shocks Front	Within Specification	•
Shock Mountings Front	Within Specification	•
Shocks Rear	Within Specification	lacksquare
Stabilizer Links	Within Specification	•
Wheel Bearings	Within Specification	•
Bearing Hubs	Within Specification	•
Control Arms	Within Specification	•
Sideshafts/Seal	No Visible Leaks	•
Propshaft	Not Applicable	•
Wheel Nuts/Studs	Within Specification	
Tyres & Spare	Within Specification	•
Mag Wheels/Hub Caps	Within Specification	lacksquare

Transmission & Clutch		
Clutch Kit	Not Applicable	•
Clutch Master	Not Applicable	•
Clutch Slave	Not Applicable	<b>T</b>
Clutch Cable	Not Applicable	•
Gearbox	Within Specification	•
Gear & Diff oil	Not Applicable	•
Auto Transmission	Within Specification	•
Gear Selector	Within Specification	•
Gear Linkages	Within Specification	<b>T</b>

Ignition System		
Diagnostics	No Fault Code	•
Cyl Leakage Test	No Visible Leaks	<b>~</b>
Road Test	Within Specification	-
Handling	Within Specification	<b>T</b>

Bosch Technician	General Comments
Elias Makubela	
NEW Technician	Date of Inspection



**Concluding Remarks** 

